
PuMA measure

Brake fluid, container

US 64627461-02 - 03/02/21

Complaint:

There have been cases where brake fluid from a new container no longer satisfies requirements (contains deposits, water, etc.), although the regular exchanging period has been observed.

Cause

Using brake fluid from large containers is no longer allowed. Since fluid begins aging as soon as the container is opened, it cannot be ruled out that the fluid used for a motorcycle is in fact aged/old.

Measure

Use only BMW brake fluid from containers sizes 0.25L or 1L. Large containers have been removed from the EPC and can no longer be ordered.

Validity information

Model series:	[EXX, K40, K42, K41, K44, K43, K46, K48, K47, R21, K49, R22, R28, A15, K51, K50, K53, K52, K54, 247, 248, K61, C1, 259, K71, K70, K73, K72, K75, E169, K80, K81, K02, K03, K09, 247E, 259S, 259R, K15, K569, K14, K17, K16, K19, BOUT, K18, 259E, 259C, K22, K21, K23, K26, K25, K28, K27, K29, R259, K589, K30, K33, K32, R13, V99]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[900010]
Production period:	-

Repair overviews

34/51/001/26116, Brake fluid, Front, , Cannot be encoded with VFC, , Checking, repairing, replacing

Attachments

Number of attachments: 3