
PuMA measure

Observe the Li-ion battery, HP / M battery tightening torque for battery terminal

US 65086508-01 - 03/02/21

Complaint:

Battery connection terminal broken off

Cause

Tightening torque too high

Measure

When tightening the battery terminal, the maximum tightening torque of 4.5 Nm must be observed. Do not use a ring spanner / open-end spanner.

Validity information

Model series:	[K51, K50, K53, K54, K67]
Engine range:	[ALL]
Body style:	[ALL]
Fault codes:	[]
Production period:	from 01/07/19

Repair overviews

Attachments

Number of attachments: 4