
PuMA measure

Inner trim frame cracked

US 65334783-01 - 02/02/21

Complaint:

Inner trim frame cracked.

Cause

The application of media, high temperatures or vibrations can lead to the inner trim frame breaking.

Measure

The inner trim frame was revised and will in future be manufactured from a higher-strength material.

The difference will be apparent from the revision index. The part numbers with the new revision index are now as follows:

46 63 8 388 421 - 07

The first parts will be available at the end of February. Please no longer install parts with revision index 06.

If a new inner trim frame breaks, please create a PuMA message.

For vehicles under the new motorcycle warranty please claim using defect code: 4663170100.

Validity information

Model series: [K67]

Engine range: [ALL]

Body style: [ALL]

Fault codes: []

Production period: -

Repair overviews

Attachments

Number of attachments: 6