



87-21-01TT - Low A/C Refrigerant

Release date: 3/12/2021

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.****Applicable Vehicles**

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
All	2015-2021	All	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2062680/1	3/12/21	87-21-01TT	Original publication.

Technical Background

Low refrigerant, possible receiver drier cap seal.

Service

Vehicles that do not exhibit a leak after installing dye may have a small leak at the receiver drier cap. Due to the receiver drier absorbing the dye, it will not always be present right away.

For issues of refrigerant loss where dye is not present, perform Technical Bulletin 87-20-02 (2061094) Refrigerant Leak Diagnosis Using Nitrogen to try and locate the leak. Spray soapy water around all the refrigerant connections and components including the receiver drier cap seal location.

Additional Information

© 2021 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.