Model Series 167: Cracks In ARTI-CO Seat Cushion Cover On Front Seat

Topic number

LI91.18-P-071629

Version

3

Function group

91.18 - Seat covers

2/18/21

Validity

Model series 167 ARTICO man-made leather upholstery or ARTICO man-made leather upholstery/DINAMICA microfiber

Reason for change Adjusting remedy to call for PTSS cases again

Complaint

The seat cushion cover on the front seat cracks when side bolster is equipped with "ARTICO man-made leather upholstery".

For vehicles equipped with "ARTICO man-made leather upholstery/DINAMICA microfiber - black (601A)", please create a PTSS case straight away.

Note: This is the seat covering with NO PERFORATIONS in the man-made leather

Attachments				
File	Description			
example1.jpg	Example 1			
example2.jpg	Example 2			
example3.jpg	Example 3			

Cause

If this complaint occurs with the "ARTICO man-made leather upholstery/DINAMICA microfiber - black (601A)" which has NO PERFORATIONS, open a PTSS case with the following information:

- + Images of the seat cover
- + Images of the seat cushion padding (foam)
- + Manufacturing date of the seat cushion cover
- + Mileage

Remedy

Please open a PTSS case with photos of the cover. Please do not replace the cover until instructed to.

XENTRY TIPS

Symptoms		
Body > Seat > Seat cover > Chafed through		
Body > Seat > Seat cover > Detaches		

Operation numbers/damage codes						
Op. no.	Operation text	Time	Damage code	Note		
			91A0407			
			91N0407			