

# McLaren Speedtail – Replace Auxiliary USB Board


**Bulletin type:** Service Campaign Bulletin  
**Reference number:** SCB 23 M 002  
**Attention:** Retailer Service Managers and Retailer Technicians  
**Affected vehicles:** McLaren Speedtail  
**Situation:** Installed part cannot be used  
**Procedure:** To action affected vehicles during next Retailer visit. Please refer to the information outlined in this document to replace the auxiliary USB board  
**Date:** 11<sup>th</sup> March 2021

This Service Campaign Bulletin will cover:

1. Overview
2. Parts Information
3. Procedure
4. Warranty Information
5. Affected Vehicles

## 1. Overview

A known number of McLaren Speedtail vehicles were fitted with auxiliary USB boards with a blanking cover installed over them to prevent usage. A new part has now been released for installation in the affected vehicles, so that the functionality can be utilised.



Auxiliary USB board (1)

## 2. Parts Information

The below part is required to action this repair, which can be ordered via Unipart.

Part Number	Part Description	Quantity Required
16MB225CP	Auxiliary USB board	1

## 3. Procedure

To perform the required work, follow SIS document: GA-RM-09M021-07-001 - Remove/Install Auxiliary USB board

## 4. Warranty Information

Please follow the relevant instructions below depending on which repair is being carried out:

Description	Repair Time
McLaren Speedtail – Replace auxiliary USB board	0.65 hours

The removed part(s) must be rendered unusable and can then be securely disposed of once the claim has been approved. These parts are not required to be stored according to the standard McLaren Warranty policy for this action.

**CARE POINT:** The work instruction and related labour time may be different from work instructions in the Service Information System (SIS). When you do this work you must refer only to the advice in this bulletin.

## 5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a workshop visit related to the vehicle.

Your Regional Aftersales Manager will also contact you with a list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

Best regards,

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.