
McLaren Speedtail – Check passenger occupant warning light operation

Bulletin type:	Service Campaign Bulletin
Reference number:	SCB 23 M 003
Attention:	Retailer Service Managers and Retailer Technicians
Affected vehicles:	McLaren Speedtail
Situation:	Potential for the passenger occupant seatbelt warning light to remain on, although the occupant is correctly seated with the seatbelt correctly buckled
Procedure:	To action affected vehicles during next Retailer visit. Please refer to the information outlined in this document to perform a check and corrective measure if necessary
Date:	11 th March 2021

This Service Campaign Bulletin will cover:

-
1. Overview
 2. Parts Information
 3. Procedure
 4. Warranty Information
 5. Affected Vehicles
-

1. Overview

Through continuous product quality monitoring, it has been identified that a number of McLaren Speedtail vehicles may have an incorrect operation of the passenger occupant seatbelt warning. The warning light may remain on although the passenger is correctly seated with the seatbelt correctly buckled. Therefore, a check of the system and potential rework may be required.

2. Parts Information

No parts are required to action this repair.

3. Procedure

To perform the required work, document SCB 23 M 003 WI (attached with this Bulletin) contains the relevant work instructions and care points to ensure the required repair is carried out to bring the vehicle up to the current manufacturing standard.

4. Warranty Information

Please follow the relevant instructions below depending on which repair is being carried out:

Description	Repair Time
McLaren Speedtail - Check seatbelt operation	0.05 hours
McLaren Speedtail - Carry out corrective measure*	0.45*

*If the corrective measure is performed, add an additional labour line in the claim for the work at the time quoted

CARE POINT: The work instruction and related labour time may be different from work instructions in the Service Information System (SIS). When you do this work you must refer only to the advice in this bulletin.

5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a workshop visit related to the vehicle.

Your Regional Aftersales Manager will also contact you with a list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

Best regards,

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle. Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.