



SERVICE ADVISORY

Release Date: March 16, 2021

Communication #: ISA-21-01

Expiration Date: March 16, 2022

IND

Model Year(s): 2022

— Confidential and Proprietary —

VERSION: R01 (March 16, 2021)

IMPORTANT

If you are working with a printed copy, please verify you have the most current version of this document.

SUBJECT: CHIEF FORK NOISE

PURPOSE

Indian Motorcycle found that some 2022 Chief models can exhibit a noise in the front of the motorcycle when operating slowly on rough or bumpy road conditions. The sound can be difficult to properly diagnose as it may resemble a metallic clicking in the front headlight area.

- The sound is coming from the bypass valve within the front suspension and occurs when switching between compression and rebound.
- The sound can be amplified by the fender shape on some motorcycles.
- The sound does not affect the performance of the motorcycle.

At the time of availability, Indian Motorcycle will update this communication with repair, parts and claim information, if required.

AFFECTED MODELS

MODEL YEAR	MODELS	VEHICLE IDENTIFICATION NUMBER RANGE
2022	Chief	Reference Unit Inquiry on the dealer website or the Service Communications list on the STOP site to look up affected VINs.
	Chief Bobber	
	Super Chief	

FEEDBACK FORM

A feedback form has been created for the technician to provide Polaris with an overall satisfaction rating for the instructions, provide comments on your experience or upload pictures/video. This feedback form is viewable on a mobile device by scanning the QR code or by clicking [HERE](#) if viewing this document electronically.

