

CAMPAIGN LAUNCH STATUS

N544 UPDATE PRIOR TO SALE – ELECTRONIC PARK BRAKE



UPDATE PRIOR TO SALE N544 - L551 L550 ELECTRONIC PARK BRAKE NOT AVAILABLE WARNING

AFFECTED MODELS	21MY Range Rover Evoque and Discovery Sport
VOLUME AFFECTED	32 USA 1 CAN
REPAIR	On certain 2021 model year Discovery Sport and Range Rover Evoque vehicles, when the vehicle ignition is switched off, the EPB will not automatically apply as expected.. The vehicles will require the customer feature to be enabled using the ABS ECU functions menu in Pathfinder
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	February 5 th , 2021
Notes	28 units are in retailer inventory. The repair was previously published in SSM 75204



PRINTED COPIES ARE UNCONTROLLED