

- LiveWire – Vehicle Supervisory Controller (VSC) – Electrically Erasable Programmable Read Only Memory (EEPROM) error notification in vehicle status

NOTE

2021 vehicles must use **TECHLINK 3** (PART NUMBER: HD-48650-TL3) (connects to Red DLC on the vehicle).

Version 21.1

New Features:

- Provide support for 2021 vehicles: FLHRXS, FLHXS, FLTRXS, FLFBS, FXBBS, FLHXSE, FLHTKSE, FLTRXSE, FLHTCUTGSE
 - VIN support
 - Reflash
 - System info/date items
 - Active diagnostics
 - Guided diagnostics
 - Diagnostic Trouble Codes (DTCs)
- Provide support for Bluetooth dongle (BTD).

Changes:

- Update 2021 Guided Diagnostics to correct for missing pictures and wiring diagrams.
- Correct motorcycle condition report for 2021 Trike hot idle temperature.

NOTE

2021 vehicles must use **TECHLINK 3** (PART NUMBER: HD-48650-TL3) (connects to Red DLC on the vehicle).

Version 21.00

New Features:

- Provide support for 2021 vehicles.
 - VIN support
 - Reflash
 - System info/date items
 - Active diagnostics
 - Guided diagnostics
 - DTCs
- Provide support for "Harley-Davidson Audio" equipped vehicles.
- Add refresh button on toolbar to allow user to re-scan for modules.

Changes:

- N/A

Required Dealer Action

Techlink

- The **TECHLINK 3** (PART NUMBER: HD-48650-TL3) will support CAN protocol vehicles (6-pin DLC) at launch. J-1850 protocol (4-pin DLC) support is planned for early 2020.

- Techlink 3 will not support Harley-Davidson Buell, Vereinigte DEUTA-OTA (VDO) and Magneti Marelli vehicles (4-pin DLC). Support for those vehicles is available via **TECHLINK II** (PART NUMBER: HD-48650-1).

- 2021 vehicles must use **TECHLINK 3** (PART NUMBER: HD-48650-TL3) (connects to Red DLC on the vehicle).

Digital Technician™ II

- The Digital Technician II software version updates are automatic and occur while connected to the Internet.
- If an internet connection is lost, the download continues from where it stopped.
- If the Digital Technician II software is open, the application prompts the user to exit before the install can continue.
- All Digital Technician II software updates are deployed automatically via the XMS agent software and require a minimum model year software version (example: Model Year 2021 = minimum version v21.0).