

TECHNICAL TOPICS

ELECTRICAL



| OS 2.0.8 SOTA UPDATE | 20-21MY L663 Defender |
|---|---|
| <p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> OS 2.0.8 VDC 9.1 Automatic Update <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> VDC 9.1c 20MY L663 VDC 9.1d 21MY L663 <p><u>Status:</u></p> <ul style="list-style-type: none"> Release notes can be found on TOPIx under the Documents >>Software tab Software Updates <ul style="list-style-type: none"> Reports of software updates failing and causing internal quiescent drain to the Telematic Control Unit Module (TCU) Customer Personalisation Settings: <ul style="list-style-type: none"> Incorrect seat and steering positions being set from the customers personalisation settings Improvements for the temperature control to prevent low temperature being set by the smart settings feature | <p>DETAILS</p> <p>History Update Progress</p> <hr/> <p>TCU</p> <ul style="list-style-type: none"> OS 2.0.8 P9DT (Update to - L8B2-70488-DT) OS 2.0.5 P2DR (Update to - L8B2-70488-DR) OS 2.0.3 P5DP (Update to - L8B2-70488-DP) OS 2.0.1 P9DN (Update to - L8B2-70488-DN) |

