


# TECHNICAL TOPICS

## POWERTRAIN



Noise From Front Halfshaft	20MY – Onward RR Evoque
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>There is a noise from the vehicle while driving.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>The noise is isolated to the front halfshaft bearing area.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>Do not replace the halfshaft due to scoring on the bearing race due to rotation of the bearing within the strap.</li> <li>Reference section 205-04 of the TOPIx WSM for repair instructions.</li> </ul>	 <hr/> 