

## TECHNICAL TOPICS

### BODY/CHASSIS



#### Seat Cover Staining / Discoloration

20 – 21MY Defender

##### Customer Voice:

- A customer may report that the seat cover is becoming stained or discolored.

##### Technical Description:

- This may be caused by a numerous different factors. One of them being incorrect amount of fabric treatment applied during manufacturing.

##### Status:

- A special seat cover cleaning procedure has been developed to address this concern.
- TSB JLRTB02070NAS1 has been published to address this concern.
- Should a customer express a concern, please refer to this TSB and make sure that the instructions are fully followed.

