## **TECHNICAL TOPICS BODY/CHASSIS**





Sunroof Only Opens Partially After Expedition Roof Rack Installation	20 – 21MY Defender
<ul> <li>Customer Voice:         <ul> <li>A customer may report after the accessory Expedition Roof Rack has been installed, that the sunroof opening panel only partially opens and does not open fully as before.</li> </ul> </li> <li>Technical Description:         <ul> <li>Originally the accessory installation instructions for the Expedition Roof Rack included configuration with PATHFINDER.</li> </ul> </li> <li>Status:         <ul> <li>The installation instructions have been updated to remove the configuration with PATHFINDER.</li> <li>Should a customer express a concern, refer to this SSM75250 to restore the sunroof opening panel operation to original operation.</li> </ul> </li> </ul>	Total and the second se
Image:	37