

TECHNICAL TOPICS

BODY/CHASSIS



Tapping Noise from A-Pillar Area

20 – 21MY Defender

Customer Voice:

- A customer may report a tapping type noise while driving from the windshield area.

Technical Description:

- When traveling at speeds over 37 mph (60 km/h) a constant low level tapping noise may be heard coming from the A-pillar area due to insufficient windshield molding clip tension.

Status:

- TSB JLRTB02058NAS1 is going through sign-off to provide robust repair guidance to address tapping noise concerns from the A-pillar area
- Should a customer express a concern, please refer to this TSB for guidance on repair.

