TECHNICAL TOPICS BODY/CHASSIS





HVAC Evaporator Refrigerant Leak	20MY RR Evoque & Discovery Sport
 <u>Customer Voice</u>: A customer may report a lack of cooling from the air conditioning system. <u>Technical Description</u>: This may be caused by an air conditioning system that has become low on refrigerant due to a leak from the evaporator core. <u>Status</u>: Engineering is investigating claims regarding evaporator refrigerant leaks. To support this investigation engineering have published SSM75267 requesting an EPQR be submitted with details requested in the SSM. 	Q Image: Constrained of the second of th

PRINTED COPIES ARE UNCONTROLLED