

# TECHNICAL TOPICS

## ELECTRICAL



Automatic High Beam Disabled	20-21MY L663, 21MY Discovery Sport, Discovery, Evoque, Velar, F-PACE, E-PACE, I-PACE, XF
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>Unable to turn on auto high beam feature</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>After a short sleep cycle the auto high beam menu is set to disabled and the auto high beam will not operate.</li> <li>JLRTB02078NAS1 provides update instructions to resolve this concern</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li>A software update for the (HCM &amp; HCMB) headlamp control module A &amp; B has been released.</li> <li>This procedure requires a minimum of Pathfinder 318 or later.</li> </ul>	

