

TECHNICAL TOPICS

BODY/CHASSIS



HVAC Evaporator Refrigerant Leak

20MY RR Evoque & Discovery Sport

Customer Voice:

- A customer may report a lack of cooling from the air conditioning system.

Technical Description:

- This may be caused by an air conditioning system that has become low on refrigerant due to a leak from the evaporator core.

Status:

- Engineering is investigating claims regarding evaporator refrigerant leaks.
- To support this investigation engineering have published **SSM75267** requesting an EPQR be submitted with details requested in the SSM.

