



## TECHNICAL TOPICS

### BODY/CHASSIS



Water Leak from Windshield	17 - 20MY Discovery 15 - 19MY RR Evoque
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> <li>A customer may report water leaking into the vehicle cabin from the windshield.</li> </ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> <li>The primer layer between the windshield and the PU adhesive may fail to seal in spots allowing water to enter the vehicle cabin.</li> </ul> <p><u>Status:</u></p> <ul style="list-style-type: none"> <li><b>SSM74710</b> has been published to request an EPQR only be submitted for vehicles built after L2442747.</li> <li>EPQRs are not needed for Discovery (L462) models built before L2442747 or any RR Evoque (L538) models.</li> <li>Pictures of the windshield and glass data are however, required to be attached to the warranty claim as stated in Aftersales Bulletin NAS20.07.003</li> <li>The Workshop Manual windshield water ingress diagnostics section will be updated to reflect this.</li> </ul>	  <p style="font-size: small; text-align: center;">● - location &amp; quantity of leak path from sample</p> 