

Reference:

ITB03-053C

Date:

March 1, 2021

VOLUNTARY SERVICE CAMPAIGN FX35/FX45 REAR HATCH

CAMPAIGN I.D. #: P3132**APPLIED VEHICLES:** 2003 FX35 (S50)
2003 FX45 (S50)**APPLIED VINS:** Vehicles built between:
JNRAS08U * 3X 000014 - 002021, 100001 - 101801
JNRAS08W * 3X 000028 - 004173, 200001 - 203876
JNRBS08W * 3X 000051 - 003596, 400001 - 402363

Service Campaign ID # P3132 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # P3132.
- Discard all previous versions of ITB03-053.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
August 6, 2003	ITB03-053	Original bulletin published
May 9, 2006	ITB03-053A	Changes made throughout
January 31, 2011	ITB03-053B	PARTS INFORMATION, CLAIMS INFORMATION, and page 10 revised
March 1, 2021	ITB03-053C	Bulletin no longer active