

NTB08-051A

March 24, 2021

Date:

## **VOLUNTARY SERVICE CAMPAIGN** 2008 ALTIMA SEDAN DRIVE BELT TENSIONER BOLTS (2.5L ENGINE)

PB072 CAMPAIGN ID #: APPLIED VEHICLE: 2008 Altima Sedan (L32) with 4 cylinder 2.5L engine (Coupe and Hybrid NOT included)

## Service Campaign ID # PB072 is no longer active.

- Repair orders opened after this bulletin's published date are no longer eligible for reimbursement under Campaign ID # PB072.
- Discard all previous versions of NTB08-051.

## AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
May 24, 2008	NTB08-051	Original bulletin published
March 24, 2021	NTB08-051A	Bulletin no longer active