



Bulletin No.: PIT5744A
Published date: 03/5/2021

Preliminary Information

PIT5744A Disabling Side Blind Zone Alert and/or Park Assist Systems When Removing Pickup Box and/or Bumper

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|----------------------------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Chevrolet | Silverado 1500 (New Model) | 2019 | All | All | All | All |
| Chevrolet | Silverado | 2020 - 2021 | All | All | All | All |
| GMC | Sierra 1500 (New Model) | 2019 | All | All | All | All |
| GMC | Sierra | 2020 - 2021 | All | All | All | All |

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

| | |
|----------------------------|--|
| Involved Region or Country | North America |
| Additional Options (RPO) | UD5, UD7, or UKC |
| Condition | A customer may request the pickup box and rear bumper be removed to install an aftermarket bed or body. If the vehicle is equipped with Side Blind Zone Alert (UKC) or Park Assist (UD5/UD7) there will be "Service" messages displayed on the DIC due to missing modules and sensors after the box and rear bumper are removed. |
| Cause | Information not readily available in Service Information (SI.) |

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 168. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

| | |
|----------|--|
| Version | 1 |
| Modified | 05/26/2020 - Created per BQM Kevin Minor request. 03/5/2021 - Added 2021 Model Year |



GENERAL MOTORS