

Published date: 03/16/2021

Preliminary Information

PIP5788 DTC P2635 Set

Models

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions.
Chevrolet	Silverado 1500	2021	All	All	5.3 L82 L84 6.2 L87	All
GMC	Sierra 1500	2021	All	All	5.3 L82 L84 6.2 L87	All

Involved Region or Country	North America
Condition	Some customers may comment that the SES lamp is illuminated or was Illuminated and turned off, with no drivability concerns. During inspection Technician may notice DTC P2635.
Cause	Unknown at this time

Correction:

If you encounter a vehicle with any one of the above DTC, follow the applicable diagnostic flow chart in service information for further diagnosis and repair.

If the diagnostic does not isolate the concern no parts should be replaced, clear the codes and return it to the customer.

Engineering knows about the concern and is working on a fix.

This PI will be updated as information is gathered.

<u>Version History</u>

Version	1	
Modified	03/16/2021 - Created.	

















GENERAL MOTORS

© 2021 General Motors. All Rights Reserved.