APPLICABLE VEHICLES

2020-2021 Supra

CONDITION

Some 2020-2021 model year Supra vehicles may experience a condition where the rear hatch will not open electrically and/or from the interior manual release handle.

RECOMMENDATIONS

Toyota is currently investigating this condition and is seeking go & see candidate vehicles for inspection.

Please note the following details and open a TAS case.

- 1. What was the ambient temperature during occurrence?
- 2. Is there any additional weight mounted on the rear hatch (e.g. a spoiler)?
- 3. Does the latch release electrically?
- 4. When attempting to release electrically, does the latch make a noise?
- Does the latch release from the interior manual release?
 (NOTICE: Only attempt to release using light force. If excessive force is applied, additional damage may occur.)
- 6. Does the interior manual release cable feel stiff when pulled gently, or does it extend and rebound freely?

Once this information has been gathered, please create a TAS case, including the information above, and contact TAS for instruction prior to diagnosing or repairing of the vehicle. If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available workday.

LINK REFERENCES

This Tech Tip does not contain any link references

Expires on