

Lower Rear Engine Cover Cracked

AFFECTED VEHICLES

Year	Model	Trim Level
2022	MDX	ALL

We are receiving reports that a few dealers have found the lower rear engine cover cracked when doing the PDI. Inspect this cover as soon as the vehicles arrive at your dealer and any vehicles currently in your new car inventory. If you find a cracked cover, order, and replace the cover with (P/N 74114-TYA-A00) and promptly file a warranty claim using Labor Operation Number: 8131M1.

Promptly return the part when the call-in request is received. Your assistance is crucial to ensure the team investigating this issue receives parts to study; the earlier we can get these parts into the hands of our engineers, the quicker we can resolve this quality issue.

