



Parts Bulletin

TITLE:

Service Action S10082: Air Condition Hose Conflict

GROUP: 80	CAT/NO: S10082	REFERENCE BULLETINS: QB S10082	CAR MARKET: Canada	
COPY TO / CIRCULATIONS (PLEASE INITIAL):			ISSUE DATE: 2021-03-09	STATUS DATE: 2021-03-09
GENERAL MANAGER	PARTS MANAGER	SERVICE MANAGER	SALES MANAGER	
				Page 1 of 1

“Right first time in Time”

Reference Bulletins: QB S10082

Volvo Car of Canada LTD on behalf of Volvo Car Group, has decided to launch Service Action S10082 on certain model year 2021 - 2022 XC40 vehicles.

Volvo has identified that a conflict between the air condition pressure hose and air condition suction hose, may cause risk of chafing.

The corrective action is to replace the rubber sleeve on the air condition hose to prevent chafing.

S10082 affects 39 vehicles in Canada ONLY.

The following part numbers apply:

Part Number	Description	Qty
983750	Strip Clamp	1
31201519	Sleeve	1