

GPOP - Issue Review System

Part Number: L0000C5W

Part Description: BULB, C5W, License Plate Bulb

Issue Description: For concern of light bar bulb inoperative/burned out, please replace the entire light bar assembly (5MA21RFXA\$) instead of replacing the affected bulb and send the assembly to QEC. If possible, please indicate which side the bulb failed in the repair narrative.

Please call FCA Redacted Content prior to replacing the component (if needed).

If no response in 15 minutes, proceed with repair.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.