



STAR ONLINE PUBLICATION



Case Number: S2108000078

Release Date: 03/27/2021

Symptom/Vehicle Issue: RFHUB Replaced, Key Only Starts Vehicle When Key Is Pushed Into The Push To Start Button

Customer Complaint/Technician Observation: Tire pressure lamp blinking. Technician replaced the RFHUB module. Vehicle only starts if the key is pushed into the keyless push button.

Repair Procedure: Validate the correct keys and RFHUB parts are installed. Use the scan tool to erase and program the keys to the vehicle. Test the operation to complete.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found