# GLOBAL SAFETY FIELD INVESTIGATIONS DCS5715 URGENT - DISTRIBUTE IMMEDIATELY

Date: March 16, 2021

Subject: N202324120 - Customer Satisfaction Program

eBoost Brake Unit Assembly Damaged

Models: 2021 Chevrolet Silverado 1500

2021 GMC Sierra 1500

To: All General Motors Dealers

General Motors is releasing Customer Satisfaction Program N202324120 today. The total number of U.S. vehicles involved is approximately 20. Please see the attached bulletin for details.

## **Customer Letter Mailing**

The customer letter mailing will begin on March 30, 2021.

## **Global Warranty Management (GWM)**

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated March 17, 2021 or sooner. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS

# **Customer Satisfaction Program**

# N202324120 eBoost Brake Unit Assembly Damaged



Release Date: March 2021 Revision: 00

Attention: This program is in effect until April 30, 2023.

		Model Year			
Make	Model	From	То	RPO	Description
Chevrolet	Silverado 1500	2021	2021		
GMC	Sierra 1500				

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	On certain 2021 model year Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles may experience		
	brake function issues over time based on feedback received from the supplier concerning the condition		
	of certain eBoost brake unit assemblies.		
Correction	on Dealers are to replace the eBoost brake unit assembly.		

#### **Parts**

Quantity	Part Name	Part No.
1	Brake Master Cylinder w/ BSCM (w/ trailer braking, JL1) (eBoost unit assembly)	84926778
1	Brake Master Cylinder w/ BSCM (eBoost unit assembly)	84926779
1	Threadlocker	19369733 (US) 10953488 (CA)
1	Brake Fluid	19299570 (US) 19299571 (CA)

It is estimated that only 23 involved vehicles will require parts replaced. Due to the small number of vehicles anticipated that will need this fix and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.

**Reminder:** Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

#### **Warranty Information**

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9105570	eBoost Unit Replacement	2.8	ZFAT	N/A

#### **Service Procedure**

Replace the eBoost unit assembly. Refer to Brake Master Cylinder Replacement – With Power Brake Booster and Electronic Brake Control Module in SI.

## **Dealer Responsibility**

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this program <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this program at no charge to customers, regardless of mileage, age of vehicle, or ownership, through April 30, 2023. Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the involved vehicle listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. A

## **Customer Satisfaction Program**

## N202324120 eBoost Brake Unit Assembly Damaged



copy of the customer letter is provided in this bulletin for your use in contacting customers. Program follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, through April 30, 2023, whenever a vehicle subject to this field action enters your vehicle inventory you must take the steps necessary to ensure the program correction has been made before selling the vehicle. In addition, for vehicles entering your facility for service, you are required to ensure the customer is aware of the open field action and make every reasonable effort to implement the program correction as set forth in this bulletin prior to releasing the vehicle.

#### **Dealer Reports**

For dealers with involved vehicles, a listing has been prepared and will be available through GM GlobalConnect Maxis Field Action Reports or sent directly to export dealers. The Inventory tab of the dealer reports will contain VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will contain customer names and addresses from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this field action may be a violation of law in several states.

### Courtesy Transportation - For USA & Canada

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual for courtesy transportation program details.

#### **Customer Notification**

USA & Canada - General Motors will notify customers of this program on their vehicle (see copy of customer letter included with this bulletin).

## **Customer Satisfaction Program**

# N202324120 eBoost Brake Unit Assembly Damaged



	April 2021
This notice applies to your vehicle, VIN:	

Dear General Motors Customer:

We have learned that your 2021 model year Chevrolet Silverado 1500 or GMC Sierra 1500 vehicle may experience brake function issues over time based on feedback received from the supplier concerning the condition of certain eBoost brake unit assemblies.

Your satisfaction with your Chevrolet Silverado 1500 or GMC Sierra 1500 is very important to us, so we are announcing a program to fix this issue.

What We Will Do: Your GM dealer will replace the eBoost brake unit assembly. This service will be performed for you at no charge until April 30, 2023. After that, any applicable warranty will apply.

**What You Should Do:** To limit any possible inconvenience, we recommend that you contact your dealer as soon as possible to schedule an appointment for this repair. By scheduling an appointment, your dealer can ensure that the necessary parts will be available on your scheduled appointment date.

If you have any questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-630-2438	1-800-833-2438
GMC	1-866-996-9463	1-800-462-8583
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

We truly appreciate you taking the time to remedy your vehicle as we know your time is valuable. We want you to know that we will do our best, throughout your ownership experience, to ensure that your GM vehicle provides you many miles of enjoyable driving.

Neelie O'Connor Global Executive Director Customer Experience Operations

N202324120