



Technical Journal

TITLE:

PSCM ghost codes U2D4181 / U112B87 / U230057

REF NO: TJ 35774.3.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2021-03-09	STATUS DATE: 2021-03-18
FUNC GROUP: 6422	FUNC DESC: Steering gear, servo complete	Page 1 of 2	

“Right first time in Time”

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

* If workshop finds the DTC's PSCM-U230057, PSCM-U112B87 or PSCM-U2D4181 in the vehicle, please follow the advice under Service.

* A new PSCM software was released 2021 week 04 to reduce some ghost DTC's (such as PSCM-U230057), but a few other ghost codes PSCM-U112B87 and PSCM-U2D4181 remain.

* Work is ongoing to reduce further ghost codes in the following PSCM software, time plan is not yet known.

PSCM (Power Steering Control Module)

CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use
2V	Technician information/Software/Vehicle communication/Not for warranty use

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
PSCM	U112B87	Permanent
PSCM	U2D4181	Permanent
PSCM	U230057	Permanent



Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2021-9999		0439208-9999999	202037-999952

SERVICE:

There is no need to fault trace or repair these DTC's right now as long there are no symptoms or warning messages to the customer.

Warranty claim info:

No warranty claim accepted for a job described in this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 6422.