



SIB 21 01 21

INDIVIDUAL CLUTCH PARTS UNAVAILABLE

2021-03-19

This Service Information Bulletin replaces measure 65439876-02 **dated February 2021**.

MODEL

E-Series	Model Description	Production Date
K83	F 900 R	To July 31, 2020
K84	F 900 XR	To July 31, 2020


SITUATION

In cases where a clutch-related repair is needed, K83 and K84 motorcycles produced prior to August 1, 2020 will require the replacement of the complete clutch kit, as individual clutch parts are unavailable.

CORRECTION


For K83, K84, produced up to August 2020, no individual replacement parts will be offered for the clutch; see image "Figure 1: Previous Build Level", below.

Figure 1: Previous Build Level



For vehicles produced since August 2020, a new build level of the clutch is installed (analogous to K80, K81, K82) in the standard and replacement engines, see "Figure 2: Current Build Level", below.

Figure 2: Current Build Level



PROCEDURE

If necessary, motorcycles produced prior to August 2020 should have their clutch updated to the newer version.

For removal, please choose the K83/K84 repair instructions (first build level), or those provided with the vehicle identification number, "Install/remove or replace clutch". Take note of any special tools you may need.

The new clutch to be installed, part number 21 21 8 565 058, is identical to the clutch in models K80/K81/K82. The new clutch is installed according to the installation instructions for a K80/K81/K82 or K83/K84 (build level from August 2020) clutch under "Remove/install or replace clutch". Take note of any special tools you may need.

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in ETK which takes into account specific equipment and/or options.

Additional parts like gaskets, hardware and chemicals may be required for the complete repair.

Part Number	
21 21 8 565 058	Complete set clutch
21 21 8 392 359	Clutch nut
11 14 7 700 396	O-ring for crankshaft screw plug
11 14 8 393 581	Sealing rings (2x) for right-hand housing cover

Special Tools Required

21 4 680	Tool required for the removal of the “old version” clutch
21 4 606	Tool required for the installation of the “new version” clutch

WARRANTY INFORMATION

For affected motorcycles under the new vehicle warranty, the replacement of the “old version” clutch with the “new version” complete clutch kit can be invoiced under warranty.

Defect code

21 21 00 55 00	Clutch
----------------	--------

Labor Operation

21 21 000	Remove/install or replace clutch	10 FRU
+21 21 606	Remove/install or replace clutch	9 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 21 21 000 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[insert_drive_file ETK Bildtafel - Kupplung neuer Baustand - EPC picture plate - clutch new construction stage -.jpg](#)

[insert_drive_file ETK Bildtafel - Kupplung alter Baustand - EPC picture plate - clutch old construction stage.jpg](#)

[picture_as_pdf 21 01 21 INDIVIDUAL CLUTCH PARTS UNAVAILABLE.pdf](#)

Service Information Bulletin

Clutch

March 19, 2021

21 01 21

INDIVIDUAL CLUTCH PARTS UNAVAILABLE



**BMW
MOTORRAD**

This Service Information Bulletin replaces measure 65439876-02 dated February 2021.

MODEL

E-Series	Model Description	Production Date
K83	F 900 R	To July 31, 2020
K84	F 900 XR	To July 31, 2020


SITUATION

In cases where a clutch-related repair is needed, K83 and K84 motorcycles produced prior to August 1, 2020 will require the replacement of the complete clutch kit, as individual clutch parts are unavailable.

CORRECTION


For K83, K84, produced up to August 2020, no individual replacement parts will be offered for the clutch; see image "Figure 1: Previous Build Level", below.

Figure 1: Previous Build Level



For vehicles produced since August 2020, a new build level of the clutch is installed (analogous to K80, K81, K82) in the standard and replacement engines, see "Figure 2: Current Build Level", below.

Figure 2: Current Build Level



PROCEDURE

If necessary, motorcycles produced prior to August 2020 should have their clutch updated to the newer version.

For removal, please choose the K83/K84 repair instructions (first build level), or those provided with the vehicle identification number, "Install/remove or replace clutch". Take note of any special tools you may need.

The new clutch to be installed, part number 21 21 8 565 058, is identical to the clutch in models K80/K81/K82. The new clutch is installed according to the installation instructions for a K80/K81/K82 or K83/K84 (build level from August 2020) clutch under "Remove/install or replace clutch". Take note of any special tools you may need.

PARTS INFORMATION

Obtain and confirm the part numbers for your specific vehicle by entering the chassis number in ETK which takes into account specific equipment and/or options.

Additional parts like gaskets, hardware and chemicals may be required for the complete repair.

Part Number

21 21 8 565 058	Complete set clutch
21 21 8 392 359	Clutch nut
11 14 7 700 396	O-ring for crankshaft screw plug
11 14 8 393 581	Sealing rings (2x) for right-hand housing cover

Special Tools Required

21 4 680	Tool required for the removal of the “old version” clutch
21 4 606	Tool required for the installation of the “new version” clutch

WARRANTY INFORMATION

For affected motorcycles under the new vehicle warranty, the replacement of the “old version” clutch with the “new version” complete clutch kit can be invoiced under warranty.

Defect code

21 21 00 55 00	Clutch
----------------	--------

Labor Operation

21 21 000	Remove/install or replace clutch	10 FRU
+21 21 606	Remove/install or replace clutch	9 FRU

FRUs includes all repair procedures to complete the task with allowance for necessary ancillary tasks (e.g., visual inspection, lubrication, cleaning parts etc.) and administrative tasks.

Labor operation code 21 21 000 is a Main labor operation. If you are using a Main labor code for another repair, use the Plus code labor operation instead.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department