



SIB 61 05 21

SERVICE ACTION: WIRE ROUTING ADJUSTMENT

2021-03-23

MODEL

Model	Model Description	Production Date
K33 11	R nineT Urban G/S	To February 24, 2021

The affected vehicles have been marked with campaign number 0061490000 in AIR.

In order to determine if a specific vehicle is affected by this campaign it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

The bands holding the wiring harness in the area of the steering head are positioned incorrectly from the factory. This can cause rubbing against the steering head at maximum steering angle and could eventually cause damage to the surface of the steering head.


CORRECTION

Wire routing has been corrected at the factory starting February 25, 2021.

PROCEDURE

For vehicles that are affected, this Service Action must be carried out prior to delivery to the customer or at the next workshop visit.

Position the bands as illustrated in the image below.



WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Motorcycles, if applicable.

Defect code

00 61 49 00 00	Optimizing cable routing
----------------	--------------------------

Labor Operation

+00 60 722	Checking wiring-harness position, adjust if necessary.	3 FRU
------------	--	-------

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 61 05 21 SERVICE ACTION WIRE ROUTING ADJUSTMENT.pdf](#)

Service Information Bulletin

General Electrical Systems

March 23, 2021

61 05 21

SERVICE ACTION: WIRE ROUTING ADJUSTMENT



**BMW
MOTORRAD**

MODEL

Model	Model Description	Production Date
K33 11	R nineT Urban G/S	To February 24, 2021

The affected vehicles have been marked with campaign number 0061490000 in AIR.

In order to determine if a specific vehicle is affected by this campaign it will be necessary to verify the vehicle VIN in AIR (Aftersales Information Research). Based on the response of the system, either proceed with the repair or take no further action. Please note, open campaigns or vehicle stops may not appear in DCS Warranty Vehicle Inquiry or sales systems until 24-72 hours after they are announced, therefore AIR is always the recommended method for determining open campaigns and vehicle stops.

SITUATION

The bands holding the wiring harness in the area of the steering head are positioned incorrectly from the factory. This can cause rubbing against the steering head at maximum steering angle and could eventually cause damage to the surface of the steering head.


CORRECTION

Wire routing has been corrected at the factory starting February 25, 2021.

PROCEDURE

For vehicles that are affected, this Service Action must be carried out prior to delivery to the customer or at the next workshop visit.

Position the bands as illustrated in the image below.



WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Motorcycles, if applicable.

Defect code

00 61 49 00 00	Optimizing cable routing
----------------	--------------------------

Labor Operation

+00 60 722	Checking wiring-harness position, adjust if necessary.	3 FRU
------------	--	-------

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department