

**MODEL****SIB 66 01 21****FAULT MEMORY ENTRY: RDC TRANSMITTER - NO ID LEARNED**

2021-03-29

E-Series	Model Description
K34, K35	R 18 (All)

SITUATION

ISTA displays erroneous error code(s) which can be ignored.

The vehicle has no additional control unit for RDC 530 installed; The functionality is integrated into the keyless ride control unit - SLZ.

Nevertheless, the following faults are stored to: X_SLZ03

0x804407 - RDC Transmitter rear: no ID learned

0x804406 - RDC Transmitter front: no ID learned

CORRECTION

The fault is erroneous and will no longer be displayed with ISTA version 4.29.10 (release date: end of April 2021).

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department

Supporting Materials

[picture_as_pdf 66 01 21 Fault memory entry RDC transmitter no ID learned.pdf](#)

Service Information Bulletin

Cruise Control, Remote Control

March 29, 2021

66 01 21

FAULT MEMORY ENTRY: RDC TRANSMITTER - NO ID LEARNED



**BMW
MOTORRAD**

MODEL

E-Series	Model Description
K34, K35	R 18 (All)

SITUATION

ISTA displays erroneous error code(s) which can be ignored.

The vehicle has no additional control unit for RDC 530 installed; The functionality is integrated into the keyless ride control unit - SLZ.

Nevertheless, the following faults are stored to: X_SLZ03

0x804407 - RDC Transmitter rear: no ID learned

0x804406 - RDC Transmitter front: no ID learned

CORRECTION

The fault is erroneous and will no longer be displayed with ISTA version 4.29.10 (release date: end of April 2021).

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Contact the BMW Technical Support Group via TSARA
Warranty inquiries	Submit an IDS ticket to the Warranty Department
Parts inquiries	Submit an IDS ticket to the Motorrad Parts Department