

# McLaren Speedtail - Install Satellite Navigation Uplift Kit

|                           |                                                                                                                          |
|---------------------------|--------------------------------------------------------------------------------------------------------------------------|
| <b>Bulletin type:</b>     | Service Campaign                                                                                                         |
| <b>Reference number:</b>  | SCB 23 M 004                                                                                                             |
| <b>Attention:</b>         | Retailer Service Managers and Retailer Technicians                                                                       |
| <b>Affected vehicles:</b> | McLaren Speedtail                                                                                                        |
| <b>Situation:</b>         | Customers may experience satellite navigation performance concerns along with a 'weak GPS signal' message on the display |
| <b>Procedure:</b>         | Action affected vehicles during next Retailer visit. Please refer to the information outlined in this document.          |
| <b>Date:</b>              | 22 <sup>nd</sup> April 2021                                                                                              |

This Service Campaign Bulletin will cover:

1. Overview
2. Parts Information
3. Procedure
4. Warranty Information
5. Affected Vehicles

## 1. Overview

Through continuous product quality monitoring, it has been identified that a known number of McLaren Speedtail vehicles may experience performance concerns with the satellite navigation system, along with a 'weak GPS signal' message on the display. Re-positioning of the antenna location is required and an uplift kit is now available for affected vehicles.

## 2. Parts Information

The following part is required to action this repair, which can be ordered via Unipart.

| Part Number | Part Description   | Quantity Required |
|-------------|--------------------|-------------------|
| 23MA604CP   | Sat Nav Uplift Kit | 1                 |

## 3. Procedure

To perform the required work, document SCB 23 M 004 WI (attached with this Bulletin) contains the relevant work instructions and care points to ensure the required repair is carried out to bring the vehicle up to the latest manufacturing standard.

#### 4. Warranty Information

Submit a claim to the Warranty department following completion of the work, using the following details.

The unwanted part(s) are required to be stored according to the standard McLaren Warranty Policy.

| Description                                                 | Repair Time |
|-------------------------------------------------------------|-------------|
| McLaren Speedtail – Install Satellite Navigation Uplift Kit | 2.5 hours   |

**CARE POINT:** The work instruction and related labour time may be different from work instructions in the Service Information System (SIS). When you do this work you must refer only to the advice in this bulletin.

#### 5. Affected Vehicles

Affected vehicles will be flagged in the Retailer Portal when next opening a workshop visit related to the vehicle.

Your Regional Aftersales Manager will also contact you with a list of affected vehicles.

If you have any questions, please speak to your Regional Aftersales Manager.

Best regards,

The information contained in McLaren bulletins is for internal use only by McLaren Authorised Retailers and must not be published on external websites or social media forums etc.

Part numbers listed in McLaren bulletins are for reference only. Always check with the parts department to verify the latest part numbers.

All bulletins (Information/Campaign/Recall) issued by McLaren Automotive Limited ("McLaren") are intended only for use by technicians who have attended McLaren technical training courses. McLaren trained technicians have the equipment, tools, safety instructions and the know how to perform the job properly and safely. McLaren bulletins are written to inform McLaren technicians of conditions that may occur on some McLaren vehicles, or to provide information that could assist diagnosing a McLaren vehicle.