

SSM 49723: 2021 Corsair - Passenger Seat Massage Inoperative - Built On 4-Jan-2021 And Through 19-Mar-2021

Some 2021 Corsair vehicles built on 4-Jan-2021 and through 19-Mar-2021 equipped with perfect position seats may exhibit the massage feature operating incorrectly on the passenger seat. Inform the customer engineering is aware of the concern and is working on a fix. Schedule a follow-up appointment for the 3rd quarter of 2021. Monitor OASIS for updates.

Vehicles:

2021 Corsair (CX483) (TF) 2017-2021 F-Super Duty (P558) NA (FE)