

Subject: Engineering Information – Front Turn Signal Bulb Inoperative

This PI has been revised to end the need for information from the field. Please discard PIE0553B.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Equinox	2020	2020	-	-	-	-

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	4
Modified	Released February 11, 2020 Revised April 17, 2020 – Updated the Contact Information. Revised September 28, 2020 – Added picture above Step 1. Revised March 17, 2021 – Ended the need for further information from the field.