

## Procedure for ordering an electrohydraulic controller unit (EHS) for TRANSMISSION 725.0 with TRANSMISSION ID between 7250\*\*03964176 and 7250\*\*03977392.

---

Topic number	LI27.35-P-072629
Version	1
Function group	27.35 - Valve body
Date	3/12/21
Validity	CARS WITH TRANSMISSION 725.0
Reason for change	Correction due to illustration error in PDF

---

### Complaint

When ordering the electrohydraulic controller unit (EHS) using the part number stated on the EHS, the wrong parts may be ordered.

### Cause

In the case of transmissions of type 725.0

with TRANSMISSION ID

between 7250\*\*03964176 and 7250\*\*03977392, as well as

7250\*\*03980431,

7250\*\*03980433,

7250\*\*03982842,

the EHS units with part number A 725 270 19 05 and 280121S (see picture) may have an incorrect laser mark.

The hardware is OK. This is purely a matter of incorrect labeling!

### Remedy

In the event of a concern with the electrohydraulic unit, please order the relevant EHS using the vehicle identification number in XENTRY Parts Information.

Symptoms
Power transmission > Automatic transmission > Function > Malfunction
Power transmission > Automatic transmission > Function > Electrical fault/Fault code
Power transmission > Automatic transmission > Function > Shifting is rough
Power transmission > Automatic transmission > Function > Shifting is not performed or is delayed

# XENTRY TIPS

---

Power transmission > Automatic transmission > Function > Poor shift quality

## Operation numbers/damage codes

Op. no.	Operation text	Time	Damage code	Note
---------	----------------	------	-------------	------