

# **Technical Service Bulletin**

#### PSS 91 MIB3: Detailed intersection map in the instrument cluster/HUD flickers

91 21 92 2062942/2 April 21, 2021. Supersedes Technical Service Bulletin Group 91 number 21-89 dated April 9, 2021 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
A6, A6 Avant, S6, RS 6, RS 6 Avant, A7, S7, RS 7, A8, S8, Q8, SQ8, Audi e-tron quattro, and Audi e-tron Sportback	2021	All	MIB3

# Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised title (Corrected from MIB2+ to MIB3)		
1	04/09/2021	Initial publication		

**Customer states:** 

- The detailed intersection map displayed in the Audi virtual cockpit flickers.
- The detailed intersection map displayed on the HUD flickers as well.

## **Technical Background**

A software related issue can cause the display windows to flicker.

# **Production Solution**

Not applicable.

<sup>© 2021</sup> Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



# **Technical Service Bulletin**

#### Service

- 1. Explain to the customer that a solution is forthcoming for the 4th quarter of 2021 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
- 2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

### Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## **Additional Information**

All part and service references provided in this TSB (2062942) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.