

ATTENTION:

- GENERAL MANAGER
- PARTS MANAGER
- CLAIMS PERSONNEL
- SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2021 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

SERVICE INFORMATION BULLETIN

APPLICABILITY: 2020MY WRX
SUBJECT: OBDII Diagnostic Connector and Body Integrated Unit (BIU) Mounting Brackets- Design Changes

NUMBER: 07-193-21
DATE: 04/07/21

INTRODUCTION:


This Service Information Bulletin announces design changes made to the OBDII diagnostic connector and BIU mounting brackets to meet new OBD regulations for rigidity.

PRODUCTION CHANGE INFORMATION:

The new brackets were incorporated into production starting with VIN **L9834056**.

PART INFORMATION:

REMINDER: Always order the most up-to-date replacement parts based on the specific VIN being repaired.



Description	NEW Part Numbers	OLD Part Numbers
BRACKET-INTEGRATED UNIT	88283VA020	88283VA010
CONNECTOR BRACKET-OBDII	81041VA060	81041FJ030

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

Subaru of America, Inc. is ISO 14001 Compliant

ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.

Continued...

IMPORTANT NOTES:

- The NEW parts are interchangeable with the OLD parts AS A SET ONLY.
- Never install the OLD parts on a vehicle originally fitted with the NEW parts.
- Component parts are NOT interchangeable between NEW and OLD.

SERVICE PROCEDURE / INFORMATION:

REMINDER: Customer satisfaction and retention starts with performing quality repairs.

The service procedures for replacing these brackets remains unchanged. Always refer to STIS and review the full requirements of the repair being performed. The Service Manual procedures contain information critical to performing an effective repair the first time, every time.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.