

Y1A Taycan PCM Displays German Language Unexpectedly

Vehicles Affected

Models	Model Year	Model Type	VIN Range	Vehicle-Specific Equipment
Taycan	As of 2020 up to 2021	Y1A	N/A	N/A

Revision History

Revision	Release Date	Changes
0	April 5, 2021	Original document

Condition

The customer reports that one or more of the PCM displays shows German language despite the customer not selecting German. (Please see figure 1.)

The workshop confirms this condition. Usually this condition occurs at startup.




Figure 1

Technical Background

The PCM tries to load text for all applications when the vehicle network wakes up after a full sleep. Sometimes, this load attempt occurs when the system is not yet fully ready. In this case, the PCM may have to load some of the text in the default language (German) and reattempt the text load later. If the customer looks at the display before it refreshes, there may be unexpected German text present.

This may occur at startup after the PCM central computer has been asleep.
(Generally, the PCM sleeps 15-30 minutes after vehicle shutoff).

Service Information

Shortly after startup, the correct text will become available. The customer can wait for just a little while and then force a display refresh by changing screens.

There is no repair necessary. This is not a bug.

Search Items

Taycan, German, English, Spanish, French, display, language

Important Notice: Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.