

**Y1A Taycan PCM Displays 'Check SiriusXM Antenna' Message**

**Vehicles Affected**

| Models | Model Year            | Model Type | VIN Range | Vehicle-Specific Equipment |
|--------|-----------------------|------------|-----------|----------------------------|
| Taycan | As of 2020 up to 2021 | Y1A        | N/A       | N/A                        |

**Revision History**

| Revision | Release Date  | Changes           |
|----------|---------------|-------------------|
| 0        | April 6, 2021 | Original document |

**Condition**

The customer reports the following message for SiriusXM antenna:

"Please check your SiriusXM antenna."  
(Please see figure 1.)

The workshop confirms this condition occurs at start up. The PCM displays this message for only a few seconds. The message does not return during the drive cycle.

Of note, the SiriusXM service functions normally and music/programming playback continues as expected. This message is the only symptom for this condition.




Figure 1

### Technical Background

The PCM displays this message in error. This message does not indicate a known issue with the SDARS antenna. The customer can ignore it and continue to enjoy SiriusXM programming.

In this condition, the customer will observe this message after a bus wake-up following a complete sleep cycle.

### Service Information

Porsche is analyzing this condition and working to remove this message. There is no recommended workshop action at this time. The workshop should not exchange parts.

When new information is available, we will update this bulletin.

### Search Items

Taycan, SXM, XM, satellite, antenna, SDARS, PCM6, warning

**Important Notice:** Technical Bulletins issued by Porsche Cars North America, Inc. are intended only for use by professional automotive technicians who have attended Porsche service training courses. They are written to inform those technicians of conditions that may occur on some Porsche vehicles, or to provide information that could assist in the proper servicing of a vehicle. Porsche special tools may be necessary in order to perform certain operations identified in these bulletins. Use of tools and procedures other than those Porsche recommends in these bulletins may be detrimental to the safe operation of your vehicle, and may endanger the people working on it. Properly trained Porsche technicians have the equipment, tools, safety instructions, and know-how to do the job properly and safely. Part numbers listed in these bulletins are for reference only. The work procedures updated electronically in the Porsche PIWIS diagnostic and testing device take precedence and, in the event of a discrepancy, the work procedures in the PIWIS Tester are the ones that must be followed.