

## Document Information

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.

Vehicles affected: McLaren Elva

Location: Whole Vehicle

**Topic:** Please read below some of known limitations of the existing software level 4.2. All of these topics are currently under investigation and where possible countermeasures will be included in the next software platform release. If you have any specific questions please raise them via a Technical Request.

**Condition:** Permanent

Diagnostic Trouble Codes:

## Measure

### Infotainment System

- Radio: AM/FM radio functionality is not available

### Pre-Delivery Inspection (PDI) Key Points

- Ensure the vehicle is not in lift when checking the Power Steering fluid level
- When setting the time and date use the GPS sync and then select the correct time zone
- Valet Pin is already set so no need to adjust this
- Ignore item "Preset local radio stations and check operation of all speakers" on the PDI sheet as radio is not available

### Interior

- The vehicle needs to be unlocked to open the central arm rest with the vehicle out of transport mode

## Parts Information

N/A

## Attachments

N/A

## KA Update Information

14/04/2021 – Template update

19/03/2021 – Initial Release

This document is uncontrolled when printed. Before use, check the Knowledge Base within the McLaren Retailer Portal to verify that this is the current version.