| | | GROUP | NUMBER | | |
|----------|----------------------|-----------------|--|--|--|
| | | Body Electrical | 21-BE-003H | | |
| | HYUNDAI | DATE | MODEL(S) | | |
| Technie | cal Service Bulletin | April, 2021 | Azera (HG) Elantra GT (GD) Veloster (FS) | | |
| SUBJECT: | | | | | |

Description: The warranty coverage for the clock spring has been extended to 15 years with unlimited mileage from the date of original retail delivery or date of first use, whichever occurs first. Refer to the warranty and service parts information outlined in this bulletin whenever clock spring replacement is required.



Applicable Vehicles:

Model: 2012-2014 Azera (HG) 2013-2014 Elantra GT (GD) 2012-2014 Veloster (FS)

Production Date: NOV. 29, 2011 To APR. 01, 2014 MAY 02, 2012 To APR. 28, 2014 JUL. 02, 2011 To MAY. 12, 2014

Parts Information:

| PART NAME | PART IMAGE | MODEL | MODEL PREVIOUS AFTER | | QTY |
|----------------------|------------|-----------------|----------------------|----------------|------------------|
| Clock Spring | | Elantra GT (GD) | 93490-1W120 | 93490-A4120FFF | 1 |
| | | Azera (HG) | 93490-3V120 | 93490-A4120FFF | 1 |
| | | | 93490-3V125 | 93490-A4120FFF | 1 |
| | | Veloster (FS) | 93490-3V110 | 93490-B2110FFF | 1 |
| Steering Lock Nut | | All | N/A | 56195-2F000 | 1 per vehicle |

Warranty Information:

| MODEL | OP CODE | OPERATION | OP TIME | CAUSAL PART | NATURE CODE | CAUSE CODE |
|--------------------|----------|--|---------|----------------|----------------|---------------|
| All | 10D008R0 | CLOCK SPRING DIAGNOSIS ONLY | 0.3M/H | 56195-2F000 | I3R | ZZ3 |
| Azera (HG) | 10D008R5 | | 0.6M/H | 93490-A4120FFF | I3R | ZZ3 |
| Elantra GT (GD) | 10D008R6 | CLOCK SPRING DIAGNOSIS AND REPLACEMENT | 0.5M/H | 93490-A4120FFF | I3R | ZZ3 |
| Veloster (FS) | 10D008R2 | _ | 0.7M/H | 93490-B2110FFF | I3R | ZZ3 |

NOTE 1: Submit Claim on Campaign Claim Entry Screen **NOTE 2:** If a part is found in need of replacement while performing TXXJ, and the affected part is still under warranty, submit a separate claim using the same Repair Order. If the affected part is out of warranty, submit a Prior Approval Request for goodwill consideration prior to performing the work.