



TECHNICAL BULLETIN

02 APR 2021

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Land Rover service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

This reissue replaces all previous versions. Please destroy all previous versions.

This bulletin supersedes TSB LTB00862NAS1/2016 dated 29 JAN 2016, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

Changes are highlighted in blue

SECTION:

501-00

SUBJECT /CONCERN:

RESCINDED - Second Row Seating Center Arm Rest Operating Handle Adrift/Broken -
RESCINDED

AFFECTED VEHICLE RANGE:

| MODEL: | MODEL YEAR: | VIN: | ASSEMBLY PLANT: |
|------------------------|--------------|----------------|-----------------|
| Range Rover Sport (LW) | 2014 Onwards | 001154 Onwards | Solihull |
| Range Rover (LG) | 2013 Onwards | 001204 Onwards | Solihull |

MARKETS:

NORTH AMERICA

**CONDITION
SUMMARY:****SITUATION:**

This bulletin has been rescinded with immediate effect. The content previously detailed within this bulletin can now be found in the TOPlx workshop manual, (see TOPlx workshop manual section 501-10: Removal and Installation - Rear Seat Armrest Operating Handle).

CAUSE:

N/A

ACTION:

N/A