

SERVICE ACTION

Reference number:	SA-43-1501	Issued: 19 March, 2021
Subject:	ABS Module Replacement	
Model(s):	DBX	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

Aston Martin has identified a small number of DBX vehicles that must have the ABS module replaced. These vehicles have a development ABS module installed which can disable the vehicle when new software is flashed to the module.

Note: There are no risks to safety when a vehicle is driven with a development ABS module.

Do the workshop procedure that follows to install a new ABS module.

Workshop Procedure

1. Replace the ABS module (refer to Workshop Manual Procedure 43.05.AD).

Warranty Data

Procedure and Labour Time

Description	Labour Time
Replace the ABS module	2.2

Part Data

Description	Part Number	Quantity
ABS Module	MY83-2C353-AA	1

Note: The availability of parts may be limited until 30/04/21. Please contact Parts Operations for availability before an order is placed.

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.