

## QUARANTINE NOTICE

|                   |  |  |
|-------------------|--|--|
| Reference number: | QN-43-1501   | Issued: 19 March, 2021                         |
| Subject:          | ABS Module Replacement   |  |
| Model(s):         | DBX  |  |
| VIN Range:        | Refer to the separately published list of affected Vehicle Identification Numbers (VINs) |  |
| Applicable to:    | All Dealers  |  |
| Distribute to:    | After Sales Manager<br>Executive Manager<br>Service Manager<br>Sales Manager             | Warranty Staff<br>Technician(s)<br>Parts Staff |

### Reason for this Quarantine Notice

Aston Martin has identified a small number of DBX vehicles that must have the ABS module replaced. These vehicles have a development ABS module installed which can disable the vehicle when new software is flashed to the module.

**Note: There are no risks to safety when a vehicle is driven with a development ABS module.**

Do the workshop procedure that follows to install a new ABS module.

### Workshop Procedure

1. Replace the ABS module (refer to Workshop Manual Procedure 43.05.AD).

### Warranty Data

#### Procedure and Labour Time

| Description            | Labour Time |
|------------------------|-------------|
| Replace the ABS module | 2.2         |

### Part Data

| Description | Part Number   | Quantity |
|-------------|---------------|----------|
| ABS Module  | MY83-2C353-AA | 1        |

**Note: The availability of parts may be limited until 30/04/21. Please contact Parts Operations for availability before an order is placed.**

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.