

SERVICE BULLETIN

Reference number:	SB-19-1511	Issued: 07 April, 2021
Subject:	Navigation Map Update Procedure	
Applicable to:	All Dealers	
Model(s):	DB11, Vantage 19Y and DBS Superleggera	
Distribute to:	Head of Business After Sales Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Bulletin

This service bulletin gives the process to update vehicle software for when a customer wants to update their navigation map software.

- For DB11 VIN: L00001 – L02338, do Part A of the Workshop Procedure.
- For DB11 VIN: L02339 onwards, DBS Superleggera and Vantage 19MY do Part B of the Workshop Procedure.

Workshop Procedure

Part A

1. Update the head unit software (refer to Workshop Manual Procedure 00.06.AM).

Note: The software for the head unit update is available through your regional area service manager.

2. Do the map update procedure (refer to Workshop Manual Procedure 00.06.AN).

Note: A regional USB will be required before the map update procedure can be completed. The USB will be issued to you as a Dealer tool from Parts Operations.

Part B

1. Do the map update procedure (refer to Workshop Manual Procedure 00.06.AN).

Note: A regional USB will be required before the map update procedure can be completed. The USB will be issued to you as a Dealer tool from Parts Operations.

Procedure and Labour Time

Description	Labour Time	ROT Code
Update the head unit software	0.3 hours	00.06.AM
Do the map update procedure	0.3 hours	00.06.AN

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this Quarantine Notice is written in Simplified Technical English to ASD-STE100™.