

TECHNICAL TOPICS BODY/CHASSIS



<p>Head Lamp Module DTCs</p>	<p>18 - 21MY Range Rover, RR Sport, RR Velar, RR Evoque</p>
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"> - A customer may report a lamp fault displays on the message center. <p><u>Technical Description:</u></p> <ul style="list-style-type: none"> - This may be caused by a DTC store in one of the head lamp modules. <p><u>Status:</u></p> <ul style="list-style-type: none"> - Guided Diagnostics has been updated and symptom driven pinpoint tests are available on TOPIX > Workshop Manual > Section 417-01 > Diagnosis and Testing to aid in properly diagnosing Headlamp system fault concerns and should be followed to ensure a correct first time diagnosis/ repair is made. - The usage of Guided Diagnostics for headlamp module faults is very low in the USA/ Canada markets relative to other global market usage. 	



PRINTED COPIES ARE UNCONTROLLED