

# TECHNICAL TOPICS BODY/CHASSIS



Knock Noise on Full Lock from Steering Gear	20MY RR Evoque, Discovery Sport
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>- A customer may report a knock type noise can be heard on full right lock or full left lock, turning in a tight circle and at low speeds.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>- The Inner Ball Joint contacts the steering rack housing on full lock, causing a knock noise.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>- Revised PSCM software has been developed to address this concern.</li><li>- <b>SSM 75316</b> has been published to provide repair guidance to correct this concern.</li></ul>	

