

The Harley-Davidson Motor Company logo, featuring the word "MOTOR" in a shield, "HARLEY-DAVIDSON" in a rectangular box, and "COMPANY" in a downward-pointing shield, with a registered trademark symbol (®) to the right.

2021-05-03

Purpose for Service Bulletin

Motorcycles Affected


Markets Affected

Part Numbers

Part No.	Item Description
57100348A	FAIRING LOWER, right, water cooler, outlet
57100349A	FAIRING LOWER, left, water cooler, outlet

If a cosmetic issue is discovered to the lower fairings at PDI, or a warrantable issue is seen during the warranty period, then replace both left and right side components. File the appropriate warranty claim. If one of the lower fairings is replaced as a non-warrantable concern, replacement of the opposite side would be non-warrantable as well.

Hold all claimed parts for 60 d from date of credit issued for possible field inspection and/or request to return to factory. After 60 d, destroy and discard the parts.



In the interest of preserving customer safety and satisfaction, always check for outstanding recalls whenever any motorcycle is brought into your dealership for either maintenance or service.

[illegible]